



Suzuki GSXR Pre 2003 Notice

HM Quickshifters: Superlite, Plus, Plus SS, and the HM GP will all work on Suzuki GSXRs prior to 2003. However, Suzuki GSXR models prior to 2003 have been known to show the FI light on the dashboard after the rider starts shifting with one of these quickshifters. When this occurs, the reason for it is that the ECU is not programmed to recognise the ignition cuts taking place outside of its own control as an EXPECTED event. The result is that they do what they were programmed to do: turn on the FI indicator on the dashboard, even though there is not an actual problem.

**If you have any questions or wish to speak to our Tech Team please call us on
+44 (0)1795 429168 or email info@HMQuickshifter.com**